

# Yamaha IEEE1394 Firmware V1.07 Release Notes

---

## Main Revisions and Enhancements

V1.06 to V1.07

- Now supports Yamaha Steinberg FW Driver. (n8/n12)
- Improved the function so that a sample rate other than "44.1kHz" can be available when the MOTIF XS series (including the MOTIF XS6/7/8 and MOTIF-RACK XS) functions as the clock master.

For details, refer to "for\_MOTIF\_XS\_user\_en.pdf" in the "for\_MOTIF\_XS\_user" folder.

## Version History

V1.05 to V1.06

- Added the function which enables data communication via the Yamaha Steinberg FW Driver between the computer and the MOTIF XS series to which the mLAN16E2 has already been installed.
- Solved some minor errors.

V1.04 to V1.05

- Fixed a problem that the n8/n12 and MOTIF XS series might not be able to receive the mLAN audio from two or more mLAN devices at the same time.

V1.03 to V1.04

- Fixed a problem that the computer occasionally cannot recognize the n8/n12.

V1.02 to V1.03

- Fixed a problem that the n8/n12 occasionally produces noise from the audio output jacks when changing the sampling frequency.

V1.01 to V1.02

- Fixed a problem that a Macintosh computer using Intel processors occasionally cannot recognize the connected devices.

---

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2007-2009 Yamaha Corporation All Rights Reserved.