

Yamaha Steinberg FW Driver V1.7.5 for Mac Release Notes

Contents

System Requirements for Software

Main Revisions and Enhancements

Update History

System Requirements for Software

NOTE

- The system requirements below may differ slightly depending on the particular operating system.
- For details on minimum requirements for each DAW software, refer to the respective owner's manual
- You can check the latest version information of Cubase series and their system requirements at the following website.
<http://www.steinberg.net/>
- You can check the latest version information of Yamaha Steinberg FW Driver and its system requirements at the following website.
<http://download.yamaha.com/>

OS	OS X 10.9.5/OS X 10.10.5/OS X 10.11.x/macOS 10.12.x
CPU	Intel dual core CPU
Memory	2GB or more
Interface	FireWire port
Hard disk	Free disk space of 100MB or more; high-speed hard disk

Main Revisions and Enhancements

V1.7.4 to V1.7.5

- Now supports macOS 10.12.

Update History

V1.7.3 to V1.7.4

- Yamaha Steinberg FW Driver has been confirmed to work properly on OS X 10.11.

- Changed the system requirements to the following.
OS X 10.9.5, OS X 10.10.x, OS X 10.11.x

V1.7.2 to V1.7.3

- Yamaha Steinberg FW Driver has been confirmed to work properly on OS X 10.9.
- Changed the system requirements to the following.
Mac OS X 10.6.8, 10.7.5, 10.8.x, or 10.9.x

V1.7.1-2 to V1.7.2

- Fixed a problem in which a "Failed to initialize" message appeared on the Mac having no FireWire ports, such as a MacBook Pro with Retina display.

V1.7.1 to V1.7.1-2

- Yamaha Steinberg FW Driver has been confirmed to work properly on Mac OS X 10.8.
- The installer now supports Gatekeeper.
- An uninstaller function is included. For details about using it, refer to the included Installation Guide.

V1.7.0 to V1.7.1

- Yamaha Steinberg FW Driver has been confirmed to work properly on Mac OS X 10.7.
- Solved the problem in which the devices compatible with the Yamaha Steinberg FW Driver might not be worked when connecting with the specific HDD of FireWire connection.

NOTE

Yamaha Steinberg FW Driver V1.7.1 is the version which is included in the TOOLS for MR V1.7.2-2.

V1.6.0 to V1.7.0

- Now supports 64-bit kernel of Mac OS X 10.6.
- Changed the system requirements to the following.
 - Mac OS X 10.5.8 or 10.6.x
 - Mac computer with an Intel processor

For details, refer to the "System Requirements for Software."

- Solved the problem in which a Cubase project file might not be opened after switching the sample rate to the 96kHz when connecting the three devices compatible with the Yamaha Steinberg FW Driver to the computer.

- Solved the problem in which a third device recognized by the Yamaha Steinberg FW Driver would not set the clock master after switching the sample rate from 48kHz or less to 88.2kHz or more when connecting the three devices compatible with the Yamaha Steinberg FW Driver to the computer.
- Solved the problem in which the sound from a device compatible with Yamaha Steinberg FW Driver might be delayed just after switching the clock source.
- Solved the problem in which the synchronized/unsynchronized state of the clock source might not be displayed properly in the Control Panel of the Yamaha Steinberg FW Driver.
- Solved the problem in which the error message "Failed to initialize" might be displayed when logging-on to the computer after logging-off on Mac OS X 10.5 or 10.6.
- Solved the problem in which some installed file information of the Yamaha Steinberg FW Driver might not be displayed properly when opening that file information of them on Mac OS X 10.6.

V1.5.1 to V1.6.0

- Now supports the FW16E FireWire Expansion Board.
- Improved the performance, with faster processing of the audio input and output.

V1.1.0 to V1.5.1

- Now supports Mac OS X 10.6.
- Solved the problem in which the Control Panel of Yamaha Steinberg FW Driver might not be displayed properly just after completing installation of the Yamaha Steinberg FW Driver.
- Solved the problem in which CPU load of the Yamaha Steinberg FW Driver would be high when turning off the power of the device compatible with Yamaha Steinberg FW Driver connected to the PowerPC based Mac.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2010-2016 Yamaha Corporation.

Yamaha Steinberg FW Driver V1.7.5 for Mac Release Notes

目次

ソフトウェアの動作環境

主なアップデートの内容

過去のアップデートの内容

ソフトウェアの動作環境

NOTE

- お使いの OS によっては、下記の仕様以上の条件を満たす必要があります。
- 各社 DAW の動作環境については、それぞれの取扱説明書をご参照ください。
- Cubase シリーズの最新バージョン、動作環境については、下記 URL に最新情報が掲載されています。

<http://japan.steinberg.net/>

- Yamaha Steinberg FW Driver の最新バージョン、動作環境については、下記 URL に最新情報が掲載されています。

<http://download.yamaha.com/jp/>

OS	OS X 10.9.5/OS X 10.10.5/OS X 10.11.x/macOS 10.12.x
CPU	Intel デュアルコアプロセッサ
メモリー	2GB 以上
インターフェース	FireWire ポート
ハードディスク	100MB 以上の空き容量、高速なハードディスク

主なアップデートの内容

V1.7.4 → V1.7.5

- macOS 10.12 に対応しました。

過去のアップデート内容

V1.7.3 → V1.7.4

- OS X 10.11 で動作することを確認しました。
- 動作環境を変更しました。以下の環境が必要です。

OS X 10.9.5, OS X 10.10.x, OS X 10.11.x

V1.7.2 → V1.7.3

- Mac OS X 10.9 で動作することを確認しました。
- 動作環境を変更しました。以下の環境が必要です。
Mac OS X 10.6.8, 10.7.5, 10.8.x, または 10.9.x

V1.7.1-2 → V1.7.2

- MacBook Pro Retina ディスプレイモデルなど、FireWire ポートを搭載していない Mac で、"Failed to initialize"のエラーメッセージが表示される問題を修正しました。

V1.7.1 → V1.7.1-2

- Mac OS X 10.8 で動作することを確認しました。
- インストーラーが Gatekeeper に対応しました。
- アンインストーラーを同梱しました。使用方法は同梱のインストールガイドをご参照ください。

V1.7.0 → V1.7.1

- Mac OS X 10.7 で動作することを確認しました。
- 特定の FireWire 接続の HDD を接続すると、Yamaha Steinberg FW Driver 対応機器を使用することができなくなる問題を修正しました。

NOTE

Yamaha Steinberg FW Driver V1.7.1 は、TOOLS for MR V1.7.2-2 に収録されているバージョンです。

V1.6.0 → V1.7.0

- Mac OS X 10.6 の 64 ビットカーネルに対応しました。
- 動作環境を変更しました。以下の環境が必要です。
 - ・ Mac OS X 10.5.8 または 10.6.x
 - ・ Intel プロセッサを搭載した Mac詳細は、「ソフトウェアの動作環境」をご参照ください。
- 3 台の Yamaha Steinberg FW Driver 対応機器を接続して、サンプルレートを 96kHz に切り替えた状態で Cubase のプロジェクトファイルを開くと、プロジェクトファイルが開けないことがある問題を修正しました。
- 3 台の Yamaha Steinberg FW Driver 対応機器を接続して、サンプルレートを 88.2kHz 以上から 48kHz 以下に切り替えたときに、Yamaha Steinberg FW Driver に認識される 3 台めの機器をクロックマスターにできなくなる問題を修正しました。

- クロックソースを切り替えたあと、Yamaha Steinberg FW Driver 対応機器が発音するまでに時間がかかることがある問題を修正しました。
- Yamaha Steinberg FW Driver のコントロールパネルで、クロックソースの同期/非同期が正しく表示されないことがある問題を修正しました。
- Mac OS X 10.5 および 10.6 で、ログアウトしたあとにログインすると、「Failed to initialize」というエラーメッセージが表示されることがある問題を修正しました。
- Mac OS X 10.6 で、インストールされた Yamaha Steinberg FW Driver のファイルの情報を開いたときに、表記の一部が正しく表示されない問題を修正しました。

V1.5.1 → V1.6.0

- ファイヤーワイヤーエクспанションボード「FW16E」に対応しました。
- オーディオ入出力が、より早く開始されるように改善しました。

V1.1.0 → V1.5.1

- Mac OS X 10.6 に対応しました。
- Yamaha Steinberg FW Driver のインストールが完了した直後に、「システム環境設定」から Yamaha Steinberg FW Driver のコントロールパネルが開かないことがある不具合を修正しました。
- PowerPC 搭載の Mac を使用している場合、接続している Yamaha Steinberg FW Driver 対応機器の電源をオフにすると、Yamaha Steinberg FW Driver の CPU 使用率が高くなる不具合を修正しました。

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。

(C) 2010-2016 Yamaha Corporation.