

Dante Accelerator Driver V1.0.1 for Mac Release Notes

Main Revisions and Enhancements

V1.0.0 to V1.0.1

Specification Changes

- Disabled the Pull up/Pull down settings in OS X 10.8 which do not support Pull up/Pull down.
- This driver does not support Dante Accelerator Firmware V1.0.0. Dante Accelerator Firmware V1.0.1 or later is required for use

Fixed Bug

- Solved the problem in which the audio sound would not play back properly when two audio applications were simultaneously using Dante Accelerator.

Known Issue

- If the buffer size is set to 2048 when the audio buses in the VST Connections of Nuendo are set to less than 32 channels in OS X 10.6.8, continual noise may occur. Set the value to something other than 2048.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2013 Yamaha Corporation All Rights Reserved.

Dante Accelerator Driver V1.0.1 for Mac リリースノート

主なアップデートの内容

V1.0.0 → V1.0.1

仕様変更

- OS X 10.8 では Pull up/Pull down をサポートしていないため設定を無効にしました。
- Dante Accelerator Firmware V1.0.0 とは互換性がありません。Dante Accelerator Firmware を V1.0.1 以降にアップデートしてお使いください。

修正した不具合

- Dante Accelerator を 2 つのオーディオアプリケーションで同時に使用したときに、音が正常に再生されない問題を修正しました。

既知の不具合

- OS X 10.6.8 で、Nuendo の VST コネクションのオーディオバスを 32 チャンネル以下に設定した状態でバッファーサイズを 2048 にすると、継続的にノイズが出力されることがあります。2048 以外の値を設定してください。

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。

(C) 2013 Yamaha Corporation All Rights Reserved.