

Previous RM-W Firmware

version information

V1.8.3

Fixed Bug

- Solved a problem that the microphone's battery might not be recharged when the battery power is low.
- Solved a problem that the microphone might stop charging when its battery is charging via the USB interface.